	Approved For Release	2002/06/12 : CIA-RDP68B	0307R06048062006448	's placeEGIB
M-1967			17 Jan 19	66
				Para-managagagagagagagagagagagagagagagagagaga

25X1A

TASK ORDER WORK STATEMENTS

7 October 1965

Work curtification A

# Statement of Work for

			25X1D 25X1D
	I.		
5X1D		The feasibility demonstration should	
		utilize existing off-the-shelf hardware and Government	
		facilities wherever practical.	
	II.	The efforts associated with this task order are as follows:	
		A. Determine preliminary functional requirements of the	
5X1D		suitable for use in the demonstration system testing	
		B. Determine preliminary system parameters for a	
		feasibility demonstration	
		C. Perform preliminary laboratory tests to determine the	
		suitability of off-the-shelf to satisfy	25X1D
		the functional requirements determined as a result of	
		Items A and B above.	
		D. Determine equipment and facilities available for	
		utilization in the accomplishment of the proposed	
		feasibility demonstration	

## Approved For Release 2002/06/12: CIA-RDP68B00307R000100020004-8

Task Order A (continued)

- E. Determine preliminary interface and operational requirements for equipment to be used in the demonstration test
- F. Formulate a schedule for accomplishment of the proposed feasibility demonstration.

## III. REPORTS

Prepare a final report stating the results of the efforts accomplished in association with the above scope of effort.

# TASK ORDER B

#### Statement of Work for

25X1D

I.	PURI	POSE			141.0			05V4D
	The	purpose	of	this	task order	is to	determine:	25X1D
l								

#### II. SCOPE OF EFFORT

A. OXCART Aircraft

This task order is to determine the interface requirements

This data shall include the following:

25X1D

- 1. Logic level of digital data
- 2. Timing parameters
- 3. Wave shapes
- 4. Data characteristics
- 5. Voltage and impedance levels
- 6. Interconnection cabling requirements.

Task Order B (continued)

25X1D

B. IDEALIST A	ı	r	С	r	a	İ	t
---------------	---	---	---	---	---	---	---

25X1D

This	task order is	to	determine	the	interface	require-
ments	5					
	•				This data s	shall

include the following:

- 1. Lofic level of digital data
- 2. Timing parameters
- 3. Wave shapes
- 4. Data characteristics
- 5. Voltage and impedance levels
- 6. Interconnection cabling requirements

## III. REPORTS

Prepare a final report stating the results of the efforts accomplished in association with the above scope of effort.

		TASK ORDER C	
		Statement of Work to Determine the Feasibility of	25X1E
			25X1E
	I.	PURPOSE	
		This task order is to determine	
		A. The feasibility and practicality of co-locating	
		OXCART and IDEALIST aircraft	25X1E
25X1D		and	
		B. The availability and suitability of site equipments	
		to satisfy the stated requirements.	
	II.	SCOPE OF EFFORT	
		This task order provides for the study and formulation of	25X1D
		preliminary equipment listings for support	
25X1D			
		A. Survey of existing and/or planned sites to determine:	
		1. Primary power facilities	
		2. Floor space and loading	
		3. Support utilities	
		4. Terrain topography	
		5. Antenna Farm layout	
		6. Detailed equipment inventory	
		7. Operational limitations.	
	III.	REPORTS	
		Prepare a final report, including recommendations for the	

Approved For Release 2002/06/12 : CIA-RDP68B00307R000100020004-8

equipment configuration of the various sites. These

# Approved For Release 2002/06/12 : CIA-RDP68B00307R000100020004-8

Task Order C (continued)

recommendations shall take into consideration the availability and limitations of the existing equipment and site limitations.

# Approved For Release 2002/06/12: CIA-RDP68B00307R000100020004-8

- TASK ORDER D

		Statement of Work to Determine Form Factors	25X1D 25X1D
	I.	PURPOSE  This task order is to make a preliminary determination of	25X1D
25X1D		the form factors necessary for the installation	
	II.	SCOPE OF EFFORT This task order shall define the following:	25X1D
25X1D		A. Available areas that may be used  B. Mounting Structure requirements  C. Interconnection cabling restrictions  D. Possible sources of electrical interference  E. Air flow quantity and temperature in selected areas  F. Equipment removal and replacement factors.	
	III.	REPORTS  Prepare a final report stating the results of the efforts  accomplished in association with the above scope of effort.	

## Approved For Release 2002/06/12 : CIA-RDP68B00307R000100020004-8

### TASK ORDER E

	5	Statement of Work to Determine Form Factors for IDEALIST
25X1D		Aircraft Area Installation of
25X1D		
	I.	PURPOSE  This task order is to make a preliminary determination of
		the form factors necessary for the installation
25X1D		
	II.	SCOPE OF EFFORT
		This task order shall define the following:
		A. Available areas that may be used for installation of
25X1D		
		B. Mounting Structure requirements
		C. Interconnection cabling restrictions
		D. Possible sources of electrical interference
		E. Air flow quantity and temperature in selected areas
		F. Equipment removal and replacement factors.
	III.	REPORTS
		Prepare a final report stating the results of the efforts
		accomplished in association with the above scope of effort.